

## **Government of West Bengal**

Ph.: 2248-2074

Office of the Deputy Superintending Engineer (HQ)
Public Health Engineering Directorate, 1,K.S.Roy Road,(4<sup>th</sup> Floor)
Block 'A', Room No. 13, New Secretariat Buildings, Kolkata – 700 001.

Name of the Company M/S. Dey's Medical Stores Pvt. Ltd.,

Minerva Garden Complex, Diamond Harbour Road, Joka, South 24-Pgs.

Their Ref. No.J/002/21-22

Date: 17-08-2021

In reference to the letter as cited above, the Inspection was made on 31-08-2021 in presence of the representative of the Unit and noted the following, which may please be recorded.

1.	The Desludging of the existing Septic Tank	:	Done :01(one) No.
2.	Mode of disposal of sludge	:	In trenched Pit within factory compound. (Disposal of sludge should be maintained properly as per rule).
3.	Cleaning of existing soak Pit/ Chlorination Unit	:	To be maintained properly and maintained Chlorination Chamber should be operated properly at the time of maintenance work.
4.	Chlorination Unit		Chlorination Unit – 01(one) No. [Not functioned properly]. Treated Effluent should be disposed of properly to the drainage path to avoid contamination surroundings.
5.	a)Condition of lavatory Block b)White washing/Colour washing (As per Rule 42 of West Bengal Factory rules periodical white-washing/colour-washing of the Lavatory Block should be done at least once in every period of four months and the dates should be entered in the Register Form No.(6)	:	To be maintained properly & Unhygienic situation should be avoided near the sanitation unit.  Done
6.	a) Place of drinking water.	:	To be maintained properly.
	b) Surface Drains	:	To be attended regularly as routine programme
	c) Urinals	:	To be maintained properly.
	d)Water Closets		To be maintained properly.
7.	Annual Return for the year	:	Submitted as per prescribed format – 2021.
8.	Next date of desludging will be on or before	:	August – 2022.
9.	Drinking Water:	:	
	a)Name of source/Tubewell/Corporation supply	1	Tubewell.
	b)Depth of Tube well as per declaration	:	216 mtr. (Declaration submitted).
	c)As per report dt. 22-07-2021 submitted reveals the various parameters are within the acceptable limit.		Yes
	d) Next date of drinking water test.		21-01-2022 & 20-07-2022.
	e)Whether storage tanks/cleaned regularly and maintained register.	:	It is advised to maintained register as mentioned.
	f) Details of the equipment installed.	:	Yes
10.	Water & Effluent Test Report Submitted from	:	Yes
	WBPCB approved Laboratory/PHED Laboratory. a) Report submitted for		Drinking Water/Effluent Water

N.B. In case of any of drawing (showing the Site situation Plan and Section ) should be submitted for the DY. Superintending Engineer (HQ), PHE Dte. For getting approval of Design. Sit Situation Plan and Section etc. As per Rule 37(i) of West Bengal Factories Rule – 1958 (as mended ).

For provision for drinking water in the factory proposed construction for Septic Tank. Chlorination Unit, Soak Pit, Secondary Treatment Plant, Filter Bed etc. 04(four) sets rule (34) & rule (35) of West Bengal Factories Rule, 1958(as amended) should be followed.

## **OBSERVATIONS:**

- 1. All Vent Pipe with M.P. Netted Cowl to be checked time to time avoid danger in future.
- 2. All Sanitary arrangement to be kept clean & maintained hygienic all time with spreading of bleaching powder regularly.
- 3. Septic Tank with Secondary treatment unit to be provide as per IS 2470 Part I & II 1985 as mentioned.[ i.e. vent pipe , manhole, freeboard should be provide as mentioned]. Under no circumstances should effluent from Septic tank be allowed into an open channel drain or body of water without adequate treatment [Cl. 3..3.3 IS 2470(Part - I - 1985. Proposed Secondary treatment should be construct properly as per IS 2470 (Part –II) 1985.
- 4. Next desludging should be done as per Sl. NO. 8 of this I.R. as per Factory Rules.
- 5. Surface drain should not be water logged, stagnant water should be avoided.
- 6. Useful arrangement should be done for the time of Pandemic situation to avoid Covid 19.

Please take necessary action from your end before next Inspection. Junior Engineer(HQ), PHE Dte. Dy. Superintending Engineer(HQ), PHE Dte.

Memo. No. 307/(1-3) /ST/DSE(HQ) Dated, Kolkata, the 06/9 /2021.

Government of West Bengal.

Copy forwarded for information and necessary action to:

1. The Chief Inspector of Factories, Dte. of Factories, N.S.Bldgs., (8<sup>th</sup> Floor), Kolkata-700 001. Necessary clearance certificate to be issued after compliance of the observations stated above.

2. The West Bengal Pollution Control Board, Paribesh Bhawan, Block-L, Sector-III, Salt Lake, Kolkata - 700 098.

3. The Junior Engineer, P.H.E. Dte.(HQ).

Dy. Superintending Engineer(HQ), PHE Dte. Government of West Bengal.

ND/1-9-21.

